



FIG 2





25	i tart e screen			3:09p
	Login		Probe Calibration	
	Site		Test Suites	
0.00	A	leri		\$. \$.
	,/4 lbs on spec only 2 days unt		all this week! ext inspection	1 英國時間
File l	Jtilities Help	С		

<i>k</i>	-
1 45	\supset

∭Start		2):49a
User		<u>Г</u>	
Fran Hampton Joe Persecet			
Miko Sakura	arianderira d		
Language English			
Spanish			
		Login	

F167

到Start	9:50a
Site	
37th & Alder, Portland, OR 56th & Couch, Portland, OR	- 1 12 12 12 12 12 12 12
8th & Main, Beaverton, OR	
Hon	
The state of the s	

The Control of the Co	
⊠ Start 9:50a	
	1000
Probe Calibration Check	
Calibration Home	
(Conconstant)	
	2. 可原理
And the state of t	


F169

到Start 9	51a
OPERATIONAL CATEGO	PIFE
Deliveries	
Freezer Check	
Grill Check	
Run Test-Suite-	
	No.
View Log Home	
	四 -


F16-10

						:.
7)	<u></u> ∭Sta			٠.	g):52a
ì	Test	Block:	Bathro	oms (Question	s: 4 · :
第十年,第二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十	Proce for ins quest Have check "Temp signs u	ed to spection ions. appropriate them, corarily until insets. appropriate insets.	the bath	rsonel ang Service Is		
	Yes		No		Skip Blo	ock)
	de Pel		Wales			3 4
		70	T.			


F16-11




//



F1613






F16	15

∰Start 9:	53a
Test Block: Dining hall Question: 3	/10
Corrective Actions: pick one	
Alert the staff	
Clean the floor	100 m
Clean the tables	
Other (enter your own)	
Skip	
San	ு □

F16-10

đ	. V 480			
	Start			9:52a
	Test Blo	ck: Bathroo	oms Que	stions: 4 ::
X が 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Proceed to for inspect questions Have applicheck the "Temporal signs until complete."	to the bath tions and roprlate pe em, then harily Out Of Inspection	rsonel ang Service* Is	
	garagada est Terrespondencias		\supset G	
	Yes) [No	Sk	ip Block
19				

F16-11



17

		2.02.72		
	Start		9:53a	
	Test Block:	Counter Q	uestion: 4/5	
Section Section Process	Which beve most freque by custome supra-large	ently selected rs in the		
	Sprite	Coca-cola	Dr. Pepper	
A. W. W. W.	Mountain Dew	Orange Crush	Other	
ST VALUE			Skip	:

F16 13




FIG 15

